



United States Steel Corporation  
Clairton Works  
400 State Street  
Clairton, PA 15025

June 5, 2007

Dr. Roger C. Westman  
Department of Air Quality  
Bureau of Air Pollution Control  
301 Thirty-Ninth Street  
Pittsburgh, PA 15201

U.S. Environmental Protection Agency  
Region III  
Air, Radiation & Toxics Division  
1650 Arch Street  
Philadelphia, PA 19103-2029  
ATTN: James W. Hagedorn (3AT23)

Assistant Council  
Department of Environmental Protection  
Southwest Region  
400 Waterfront Drive  
Pittsburgh, PA 15222-4745  
ATTN: Steve Repler

Department of Justice  
Environmental and Natural Resource Division  
Environmental Enforcement Section  
P.O. Box 7611  
Ben Franklin Station  
Washington, D.C. 20044  
ATTN: David Street, Esq.

Subject: USS Reference Number: 07-0120  
ACHD Reference Number: 8928  
Sulfur Plant  
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Lisa A. Roudabush  
Plant Manager  
Clairton Works

RECEIVED

JUN 15 2007

Air Protection Division (3AT23)

**NOTICE OF PLANNED OUTAGE OF EQUIPMENT**  
**ARTICLE XXI - SECTION 2108.1**

1. **USS Reference Number:** 07-0120  
**ACHD Reference Number:** 8928
2. **Date & Time of Breakdown:** Date: 06/06/07 Time: ~0800 hours
3. **Company Name:** U.S. Steel Corporation - USS Clairton Works
4. **Specific Equipment Involved or Affected:** Sulfur Plant
5. **BAPC Permit Number (if applicable):**
6. **Location:** Clairton, PA
7. **Nature and cause of breakdown:** The 101J spare sulfur plant stripper vacuum axi will be unavailable for service while repairs are made to correct a vibration problem. The 101J Axi is a redundant piece of equipment. The spare C658 Axi will carry the full load.  
  
Sulfur Plant performance will not be affected. Sulfur emissions will not increase.
8. **Identification of Emissions:**
  - A. **Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)**  
The spare C658 Axi will carry the full load. No environmental impact is expected.
  - B. **Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality).** N/A No environmental impact is expected.
  - C. **Amount of each type emitted (or likely to be emitted).**  
N/A
9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**  
The spare C658 Axi will carry the full gas flow to the plant.
10. **Facility back in operation - Date:** Time: hours

Signature *Coleen M. Davis* Date 6-5-07  
Coleen M. Davis  
Senior Environmental Control Engineer Phone: 412-233-1015